



## CCR Landfill 2024 Annual CCR Landfill Inspection Report

Flint Creek Plant, Gentry, Arkansas


**Submitted to:**

American Electric Power Service Corporation  
1 Riverside Plaza  
Columbus, OH 43215

**Submitted by:**

GEI Consultants, Inc.  
3159 Voyager Drive  
Green Bay, Wisconsin 54311  
920.455.8200

December 12, 2024  
Project 2305686  
AEP Document ID: GEVR-24-038



---

Pedro Amaya, PE  
Senior Consultant

---

Jeff Piaskowski, PE  
Senior Engineer

# 2024 Annual Inspection Report



**CCR Landfill  
Flint Creek Power Plant  
AEP Document ID: GEVR-24-038**

A handwritten signature in black ink that reads "Pedro J. Amaya". The signature is written in a cursive style.

\_\_\_\_\_  
Signature

Pedro Amaya, PE  
Senior Consultant  
GEI Consultants, Inc.

December 12, 2024

\_\_\_\_\_  
Date



I certify, to the best of my knowledge, that the information provided in this report satisfies the requirements of 40 CFR 257.84(b).

# Table of Contents

---

<b>1.</b>	<b>Introduction</b>	<b>1</b>
<b>2.</b>	<b>Description of Landfill</b>	<b>2</b>
<b>3.</b>	<b>Review of Available Information (257.84(b)(1)(i))</b>	<b>3</b>
<b>4.</b>	<b>Inspection (257.84(b)(1)(ii))</b>	<b>4</b>
4.1	Changes in Geometry Since Last Inspection (257.84(b)(2)(i))	4
4.2	Volume (257.84(b)(2)(ii))	4
4.3	Definitions of Visual Observations and Deficiencies	4
4.4	Visual Inspection (257.84(b)(1)(ii))	5
4.5	Change that Effect Stability or Operation (257.84(b)(2)(iv))	6
<b>5.</b>	<b>Summary Findings</b>	<b>7</b>
5.1	General Observations	7
5.2	Maintenance Items	7
5.3	Items to Monitor	7
<b>6.</b>	<b>Deficiencies (257.84(b)(2)(iii))</b>	<b>7</b>

## Figures

Figure 1 – Site Location Map

Figure 2 – Facility Plan

Figure 3 – Site Plan

Figure 4 – Items to be Monitored

Figure 5 – Items to be Addressed

## Appendices

Appendix A – Photolog

JRP

B:\Working\AEP\2305686 2024 Dam & Landfill Field Insps\08\_FINAL INSPECTION REPORTS\07Flint Creek\Flint Creek Landfill\2024 Flint Creek CCR Landfill.docx

# 1. Introduction

---

GEI Consultants, Inc. was retained by AEP to implement the 2024 Annual Inspection and Maintenance Program at AEP facilities. As part of the program, GEI's Pedro Amaya, P.E. performed the 2024 inspection of the CCR Landfill at the Flint Creek Power Plant in general accordance with the requirements of 40 CFR 257.84. Mr. Greg Carter and Scott Carney were the AEP facility contacts, but Scott Carney did not participate in the annual inspection. This report was prepared by Pedro Amaya, PE and Jeff Piaskowski, PE of GEI and serves as a summary of the inspection and an assessment of the general conditions of the CCR Landfill at the Flint Creek Power Plant.

The inspection was performed on November 7, 2024 with clear skies and temperatures that ranged between 48 and 68 degrees Fahrenheit. Approximately 6-inches of precipitation was recorded at the regional airport in Bentonville, Arkansas in the 7 days prior to the inspection.

The Flint Creek Power Plant is located near Gentry, Arkansas as shown on Figure 1 – Site Location Map. The facility arrangement is provided on Figure 2 – Facility Plan. The CCR Landfill and its appurtenances are shown on Figure 3 – Site Plan. The locations of items that should be monitored are provided on Figure 4 – Items to be Monitored. The locations of items that should be addressed are provided on Figure 5 – Items to be Addressed.

## 2. Description of Landfill

---

The Flint Creek CCR Landfill consists of four areas. Three areas (Areas 2, 3, and 4) are actively receiving CCR. One area (Area 1) is inactive.

The overall features of the CCR Landfill were categorized into the following components:

- Active Landfill Disposal Areas (Area 2, 3, and 4)
- Inactive Landfill Area (Area 1)
- Leachate Collection/Contact Water Pond
- Storm Water Drainage Ditches
- Closed Areas

### **3. Review of Available Information (257.84(b)(1)(i))**

A review of available information regarding the status and condition of the landfill which include files available in the operating record, such as design and construction information, previous 7-day inspection reports, and previous annual inspections has been conducted. Based on the review of the data there were no signs of actual or potential structural weakness or adverse conditions.

## 4. Inspection (257.84(b)(1)(ii))

---

### 4.1 Changes in Geometry Since Last Inspection (257.84(b)(2)(i))

No modifications have been made to the design geometry of the landfill since the last annual inspection. The geometry of the landfill has remained essentially unchanged, except for the change in topography of the active and inactive disposal areas.

### 4.2 Volume (257.84(b)(2)(ii))

The total volume of CCR disposed at the CCR Landfill as of the inspection date of was estimated to be 2,420,986 (2,355,471 last inspection + 65,515 to date) cubic yards.

### 4.3 Definitions of Visual Observations and Deficiencies

This summary of the visual observations uses terms to describe the general appearance or condition of an observed item, activity, or structure. The meaning of these terms is as follows:

- Good:** A condition or activity that is generally better or slightly better than what is minimally expected or anticipated from a design or maintenance point of view.
- Fair/Satisfactory:** A condition or activity that generally meets what is minimally expected or anticipated from a design or maintenance point of view.
- Poor:** A condition or activity that is generally below what is minimally expected or anticipated from a design or maintenance point of view.
- Minor:** A reference to an observed item (e.g. erosion, seepage, vegetation, cracks, concrete surface etc.) where the current maintenance condition is below what is normal or desired, but which is not currently causing concern from a structure safety or stability point of view.
- Significant:** A reference to an observed item (e.g. erosion, seepage, vegetation, cracks, concrete surface etc.) where the current maintenance program has neglected to improve the condition. Usually, conditions that have been identified in previous inspections, but have not been corrected.

**Excessive:** A reference to an observed item (e.g. erosion, seepage, vegetation, cracks, concrete surface etc.) where the current maintenance condition is below or worse than what is normal or desired, and which may have affected the ability of the observer to properly evaluate the structure or area being observed or which may be a concern from a structure safety or stability point of view.

This document also uses the definition of a “deficiency” as referenced in the CCR rule section §257.84(b)(5) Inspection Requirements for CCR Landfills. This definition has been assembled using the CCR rule preamble as well as guidance from MSHA, “Qualifications for Impoundment Inspection” CI-31, 2004. These guidance documents further elaborate on the definition of deficiency. Items not defined by deficiency are considered maintenance or items to be monitored.

A “deficiency” is some evidence that the CCR Unit has developed a problem that could impact its structural integrity. There are four general categories of deficiencies. These four categories are described below:

1. Uncontrolled Seepage

Uncontrolled seepage is an uncontrolled release from the unit.

2. Displacement of the Embankment

Displacement of the embankment is large scale movement of part of the pond embankment. Common signs of displacement are cracks, scarps, bulges, depressions, sinkholes, and slides.

3. Blockage of Control Features

Blockage of Control Features is the restriction of flow at spillways, decant or pipe spillways, or drains.

4. Erosion

Erosion is the gradual movement of surface material by water, wind, or ice. Erosion is considered a deficiency when it is more than a minor routine maintenance item.

#### **4.4 Visual Inspection (257.84(b)(1)(ii))**

A visual inspection of the landfill was conducted to identify signs of distress or malfunction of the landfill and appurtenant structures. Specific items inspected included structural elements of the landfill perimeter berms, temporary and final covers, side slopes, and drainage features.



Overall, the facility is in good condition. Inspection photos are included in Attachment A - Photolog.

The landfill is functioning as intended. One potential lateral crack was observed on the southern slope and should be monitored for additional movement as shown in Photograph No. 7. No other conditions were observed that may be disrupting to the safe operation of the landfill.

The landfill active area was being operated appropriately. Material is being placed and compacted systematically in lifts to allow contact stormwater to be collected, treated, and discharged as appropriate. Photograph No. 13 shows the CCR Landfill Active Area.

The leachate / contact water pond is generally in good condition as shown in Photograph No. 2 and No. 3. Some minor concrete cracking was observed as shown in Photograph No. 1 and No. 4 and should be sealed/addressed with polyurethane sealant like Sonolastic NP1 or equivalent.

The CCR Landfill downstream slope is generally in good condition. The vegetation is healthy, thick, and maintained to 12-inches or less as shown in Photograph No. 5, No. 6, No. 8, No. 10, No. 14, No. 18, No. 19, and No. 20. Some minor erosion was observed and should be addressed before it becomes significant as shown in Photograph No. 11, No. 21, No. 23, and No. 24.

The CCR Landfill drainage features are in good condition. Fabriform downchutes were intact with no signs of movement on the landfill slopes or erosion at the upstream or downstream transition areas as shown in Photograph No. 16, No. 17, No. 22, and No. 25. No blockages or vegetation was observed in any of the drainage pathways as shown in Photograph No. 16. The stormwater pond was in good condition with plenty of capacity/freeboard as shown in Photograph No. 15.

#### **4.5 Change that Effect Stability or Operation (257.84(b)(2)(iv))**

Based on interviews with plant personnel and field observations there were no changes to the landfill operation since the last annual inspection that would affect the stability of the landfill.

## 5. Summary Findings

---

### 5.1 General Observations

The following general observations were identified during the visual inspection:

1. In general, the CCR Landfill is functioning as intended design.
2. The Plant is performing inspections and maintenance as appropriate.
3. One potential longitudinal crack was observed on the southern slope. This area should be monitored for additional cracking / movement.
4. Concrete cracks were observed in two areas within the leachate / contact water pond. The cracks should be sealed with polyurethane sealant, such as Sonolastic NP1.
5. Minor erosion was observed at four areas on the side slope and should be addressed before it becomes significant.

### 5.2 Maintenance Items

The maintenance items are provided for consideration:

- Continue to maintain minor erosion rills before they become significant.
- Continue to check site culverts, ditches, outfall structures for debris/blockages to allow the site stormwater to flow as it was designed.

### 5.3 Items to be Monitored

The following items should be monitored to allow the CCR Landfill to operate as its design intended.

- Item 7 – Monitor the potential longitudinal crack on the southern slope. For reference, its length was measured to be 25-feet during the annual inspection.

### 5.4 Items to be Addressed

The following items should be addressed to allow the landfill to operate as its design intended.

- Item 1 – Address/seal the concrete cracking with polyurethane sealant, such as Sonolastic NP1.

- Item 4 – Address/seal the concrete cracking with polyurethane sealant, such as Sonolastic NP1.
- Item 11 – Address the minor erosion rills before they become significant.
- Item 21 – Address the minor erosion rills before they become significant.
- Item 23 – Address the minor erosion rills before they become significant.
- Item 24 – Address the minor erosion rills before they become significant.

## 6. Deficiencies (257.84(b)(2)(iii))

---


There were no signs of structural weakness or disruptive conditions that were observed at the time of the inspection that would require additional investigation or remedial action. There were no deficiencies noted during this inspection or during any of the periodic 7-day inspections. A deficiency is defined as either:

- uncontrolled seepage
- displacement of the embankment
- blockage of control features
- erosion, more than minor maintenance

If any of these conditions occur or if you have any questions with regard to this report, please contact Greg Carter at (903) 927-5896 / [wgcarter@aep.com](mailto:wgcarter@aep.com) or Bryan Brunton at 614-716-3090 / [bwbrunton@aep.com](mailto:bwbrunton@aep.com).

## **Figure 1 – Site Location Map**

---



2024 Annual Landfill Inspection Report  
 Flint Creek Power Plant  
 Gentry, Arkansas

American Electric Power Service Corporation  
 Columbus, OH 43215



SITE LOCATION MAP

Project 2305686

November 2024

Fig. 1


## **Figure 2 – Facility Plan**

---



**NOTES:**

1. Aerial image obtained from USDA NAIP. Image captured spring of 2021.
2. Site conditions may change over time, accuracy is not guaranteed.



2024 Annual Landfill Inspection Report  
 Flint Creek Power Plant  
 Gentry, Arkansas

American Electric Power Service Corporation  
 Columbus, OH 43215



Project 2305686

FACILITY PLAN

November 2024

Fig. 2




## Figure 3 – Site Plan

---




**LEGEND:**

 General Observation

**NOTES:**

1. Aerial image obtained from USDA NAIP. Image captured spring of 2021.
2. Points shown represent site conditions during time of inspection. Conditions may change overtime, accuracy is not guaranteed. Map should not be used for measurement.



2024 Annual Landfill Inspection Report  
 Flint Creek Power Plant  
 Gentry, Arkansas

American Electric Power Service Corporation  
 Columbus, OH 43215



Project 2305686

SITE PLAN

December 2024

Fig. 3

## **Figure 4 – Items to be Monitored**

---




**LEGEND:**

● Monitor

**NOTES:**

1. Aerial image obtained from USDA NAIP. Image captured spring of 2021.
2. Points shown represent site conditions during time of inspection. Conditions may change overtime, accuracy is not guaranteed. Map should not be used for measurement.



2024 Annual Landfill Inspection Report  
 Flint Creek Power Plant  
 Gentry, Arkansas

American Electric Power Service Corporation  
 Columbus, OH 43215



Project 2305686

ITEMS TO BE MONITORED

December 2024

Fig. 4

## **Figure 5 – Items to be Addressed**

---




**LEGEND:**

● Repair

**NOTES:**

1. Aerial image obtained from USDA NAIP. Image captured spring of 2021.
2. Points shown represent site conditions during time of inspection. Conditions may change overtime, accuracy is not guaranteed. Map should not be used for measurement.



2024 Annual Landfill Inspection Report  
 Flint Creek Power Plant  
 Gentry, Arkansas

American Electric Power Service Corporation  
 Columbus, OH 43215



Project 2305686

ITEMS TO BE ADDRESSED

December 2024

Fig. 5

## **Appendix A – Photolog**


---

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

PHOTOGRAPH NO: 1	DATE: November 7, 2024 1:50 PM	LATITUDE: 36.25797743	LONGITUDE: -94.51715092
DIRECTION: 273°		SITE LOCATION: GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Leachate Pond. Inlet Pipe. Address concrete cracks, with polyurethane sealant such Sonolastic NP1.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			





# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

<b>PHOTOGRAPH NO: 2</b>	<b>DATE:</b> November 7, 2024 1:56 PM	<b>LATITUDE:</b> 36.25752052	<b>LONGITUDE:</b> -94.51788854
<b>DIRECTION:</b> 356°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Contact Water Pond. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH NO: 3</b>	<b>DATE:</b> November 7, 2024 1:59 PM	<b>LATITUDE:</b> 36.25806131	<b>LONGITUDE:</b> -94.5178897
<b>DIRECTION:</b> 349°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Contact Water Pond. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

PHOTOGRAPH NO: 4	DATE: November 7, 2024 2:02 PM	LATITUDE: 36.25820469	LONGITUDE: -94.51676464
DIRECTION: 219°		SITE LOCATION: GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Contact Water Pond. Address concrete cracks, with polyurethane sealant such Sonolastic NP1.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686


<b>PHOTOGRAPH NO: 5</b>	<b>DATE:</b> November 7, 2024 2:05 PM	<b>LATITUDE:</b> 36.25757628	<b>LONGITUDE:</b> -94.51609106
<b>DIRECTION:</b> 281°	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Downstream Slope. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH NO: 6</b>	<b>DATE:</b> November 7, 2024 2:06 PM	<b>LATITUDE:</b> 36.25751826	<b>LONGITUDE:</b> -94.51603217
<b>DIRECTION:</b> 6°	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Downstream Slope. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686



PHOTOGRAPH NO: 7	DATE: November 7, 2024 2:12 PM	LATITUDE: 36.25733493	LONGITUDE: -94.51373109
DIRECTION: 273°		SITE LOCATION: GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope. Potential lateral crack, approx 25 ft long, along the edge of the berm, approximately 75 ft east of B5. Stable at the time of the inspection. Monitor Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686


<b>PHOTOGRAPH NO: 8</b>	<b>DATE:</b> November 7, 2024 2:18 PM	<b>LATITUDE:</b> 36.2573239	<b>LONGITUDE:</b> -94.513038
<b>DIRECTION:</b> 209°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH NO: 9</b>	<b>DATE:</b> November 7, 2024 2:20 PM	<b>LATITUDE:</b> 36.25743271	<b>LONGITUDE:</b> -94.51230031
<b>DIRECTION:</b> 219°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope / Drainage Feature. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

<b>PHOTOGRAPH No: 10</b>	<b>DATE:</b> November 7, 2024 2:26 PM	<b>LATITUDE:</b> 36.25779879	<b>LONGITUDE:</b> -94.51211408
<b>DIRECTION:</b> 262°	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Interim Cover. General Photo, Typical Conditions.	 A photograph showing a grassy slope of a landfill. The grass is a mix of green and brown, indicating some dryness. In the background, there are trees and a clear blue sky with some light clouds. A fence is visible on the right side of the slope.		
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686



PHOTOGRAPH No: 11	DATE: November 7, 2024 2:29 PM	LATITUDE: 36.25806984	LONGITUDE: -94.5129056
DIRECTION: 313°		SITE LOCATION: GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Interim Cover. Address Minor Erosion, 90 ft north of Fabiform Letdown chute.	 A vertical photograph showing a grassy field with a small, narrow erosion gully or rut running through the center. The grass is a mix of green and dry, brownish-yellow. The background shows a flat horizon under a blue sky with scattered white clouds.		
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

<b>PHOTOGRAPH No: 12</b>	<b>DATE:</b> November 7, 2024 2:37 PM	<b>LATITUDE:</b> 36.25865816	<b>LONGITUDE:</b> -94.51332411
<b>DIRECTION:</b> 161°	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Crest. Interim Cover. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH No: 13</b>	<b>DATE:</b> November 7, 2024 2:40 PM	<b>LATITUDE:</b> 36.25912305	<b>LONGITUDE:</b> -94.51315677
<b>DIRECTION:</b> 200°	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Active Area. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			





# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686


<b>PHOTOGRAPH No: 14</b>	<b>DATE:</b> November 7, 2024 2:44 PM	<b>LATITUDE:</b> 36.25948009	<b>LONGITUDE:</b> -94.51268775
<b>DIRECTION:</b> 87°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH No: 15</b>	<b>DATE:</b> November 7, 2024 2:47 PM	<b>LATITUDE:</b> 36.26037419	<b>LONGITUDE:</b> -94.5126738
<b>DIRECTION:</b> 284°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Stormwater Pond. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686


PHOTOGRAPH No: 16	DATE: November 7, 2024 2:49 PM	LATITUDE: 36.26055028	LONGITUDE: -94.51220734
DIRECTION: 267°	SITE LOCATION: GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Stormwater Pond. Inlet Works / Stormwater Features, Letdown Channel. General Photo, Typical Conditions. No debris / blockages observed.	 A photograph showing a stormwater inlet structure. The foreground is dominated by a large, dark, corrugated metal grate that has been laid out in a grid pattern on a gravelly surface. In the background, there is a concrete structure with a pipe opening, surrounded by a chain-link fence and some sparse vegetation. The overall scene appears to be a construction or maintenance site for a stormwater management system.		
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686



PHOTOGRAPH No: 17	DATE: November 7, 2024 2:55 PM	LATITUDE: 36.26076979	LONGITUDE: -94.51385411
DIRECTION: 179°		SITE LOCATION: GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope / Drainage feature. Fabri-form Letdown Channel. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686



<b>PHOTOGRAPH No: 18</b>	<b>DATE:</b> November 7, 2024 3:04 PM	<b>LATITUDE:</b> 36.26049399	<b>LONGITUDE:</b> -94.51555491
<b>DIRECTION:</b> 2°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH No: 19</b>	<b>DATE:</b> November 7, 2024 3:07 PM	<b>LATITUDE:</b> 36.26012417	<b>LONGITUDE:</b> -94.51577145
<b>DIRECTION:</b> 356°		<b>SITE LOCATION:</b> GENTRY, ARKANSAS	
<b>DESCRIPTION:</b>  Landfill Downstream Slope. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

<b>PHOTOGRAPH No: 20</b>	<b>DATE:</b> November 7, 2024 3:09 PM	<b>LATITUDE:</b> 36.26011998	<b>LONGITUDE:</b> -94.51577381
<b>DIRECTION:</b> 131°	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Stormwater Pond. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			
<b>PHOTOGRAPH No: 21</b>	<b>DATE:</b> November 7, 2024	<b>LATITUDE:</b> NA	<b>LONGITUDE:</b> NA
<b>DIRECTION:</b> NA	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Downstream Slope. Address minor erosion.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

<b>PHOTOGRAPH No: 22</b>	<b>DATE:</b> November 7, 2024	<b>LATITUDE:</b> NA	<b>LONGITUDE:</b> NA
<b>DIRECTION:</b> NA	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Stormwater Feature / Fabriform down chute. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

<b>PHOTOGRAPH No: 23</b>	<b>DATE:</b> November 7, 2024 3:04 PM	<b>LATITUDE:</b> NA	<b>LONGITUDE:</b> NA
<b>DIRECTION:</b> NA	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Downstream Slope. Address minor erosion.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			


# Photographic Log



**Project:** Flint Creek Landfill Inspection  
**Client:** American Electric Power

**GEI Project:** 2305686

<b>PHOTOGRAPH No: 24</b>	<b>DATE:</b> November 7, 2024	<b>LATITUDE:</b> NA	<b>LONGITUDE:</b> NA
<b>DIRECTION:</b> NA	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill toe of slope. Address minor erosion.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			

<b>PHOTOGRAPH No: 25</b>	<b>DATE:</b> November 7, 2024	<b>LATITUDE:</b> NA	<b>LONGITUDE:</b> NA
<b>DIRECTION:</b> NA	<b>SITE LOCATION:</b> GENTRY, ARKANSAS		
<b>DESCRIPTION:</b>  Landfill Stormwater Feature / Fabriform down chute. General Photo, Typical Conditions.			
<b>PHOTO BY:</b>  GEI CONSULTANTS, INC.			