

2025 Annual Dam and Dike Inspection Report

Fly Ash Pond

**Former Philo Power Plant
Franklin Realty Company
Philo, OH**

November 2025

Prepared for: Franklin Realty Company – Former Philo Power Plant

Prepared by: American Electric Power Service Corporation
1 Riverside Plaza
Columbus, OH 43215




2025 Annual Dam and Dike Inspection Report

Former Philo Power Plant Fly Ash Pond

PREPARED BY Blake Arthur DATE 11/13/2025
Blake Arthur, P.E.

REVIEWED BY Daniel S Murphy DATE 11/14/2025
Dan Murphy, P.E.

APPROVED BY David A. Miller DATE 12.02.2025
David A. Miller, P.E.
Director – Ash Management Services



I certify to the best of my knowledge, information and belief the information contained in this report meets the requirements of 40 CFR § 257.83(b).

Table of Contents

1.0 INTRODUCTION.....	1
2.0 DESCRIPTION OF IMPOUNDMENTS.....	2
3.0 REVIEW OF AVAILABLE INFORMATION (257.83(b)(1)(i))	3
4.0 INSPECTION (257.83(b)(1)(ii)).....	4
4.1 CHANGES IN GEOMETRY SINCE LAST INSPECTION (257.83(b)(2)(i))	4
4.2 INSTRUMENTATION (257.83(b)(2)(ii))	4
4.3 IMPOUNDMENT CHARACTERISTICS (257.83(b)(2)(iii, iv, v))	4
4.4 DEFINITIONS OF VISUAL OBSERVATIONS AND DEFICIENCIES	5
4.5 VISUAL INSPECTION (257.83(b)(2)(i))	6
4.6 CHANGES THAT EFFECT STABILITY OR OPERATION (257.83(b)(2)(vii))	6
5.0 SUMMARY OF FINDINGS	7
5.1 GENERAL OBSERVATIONS.....	7
5.2 MAINTENANCE ITEMS.....	7
5.3 ITEMS TO MONITOR/INVESTIGATE	7
5.4 DEFICIENCIES (257.83(b)(2)(vi))	7

Attachments

- Attachment A –Inspection Location Map
- Attachment B – Inspection Photographs

1.0 INTRODUCTION

This report was prepared by AEP Ash Management Services, in part, to fulfill requirements of 40 CFR 257.83 for the legacy CCR surface impoundments inspections and to provide Franklin Realty Company an evaluation of the Fly Ash Pond at the former Philo Power Plant.

The inspection was performed on November 4, 2025. The inspection party consisted of Mr. Dan Murphy, P.E., Mr. Blake Arthur, P.E., and Mr. Wesley Prince. Weather conditions during the inspection were partly cloudy, and the temperature was near 60°F. There was about 0.9 inches of rainfall recorded over the seven days prior to the inspection, with no rain the day prior to the inspection.

2.0 DESCRIPTION OF IMPOUNDMENTS

The Philo Power Plant began commercial operation in October 1924 and was closed by the middle of 1975. The Fly Ash Pond is believed to have been in operation while the plant was generating electricity. The Fly Ash Pond is separated from the Muskingum River and Duncan Run by a roughly 30-foot-tall earthen berm with an average crest elevation of approximately 702 ft-msl. The Fly Ash Pond is located northwest of the confluence of Duncan Run and the Muskingum River in Muskingum County, Ohio. The Fly Ash Pond is approximately 17 Acres and has an estimated total storage capacity of approximately 550,000 CY. While operating as an ash pond, the water elevation was controlled with a pipe and riser type outfall structure that was in the southeast corner of the pond. During an overflow condition, decant from the pond was discharged into the Muskingum River.

3.0 REVIEW OF AVAILABLE INFORMATION (257.83(b)(1)(i))

In addition to the current visual inspection, a review of available information regarding the status and condition of the Fly Ash Pond, including files available in the operating record, was conducted. Available information consists of design and construction information. Based on the findings of the current visual inspection and the review of the available data, it is concluded that the facility is performing as intended in the design documents and there were no signs of actual or potential structural weakness or adverse conditions.

4.0 INSPECTION (257.83(b)(1)(ii))

4.1 CHANGES IN GEOMETRY SINCE LAST INSPECTION (257.83(b)(2)(i))

No changes in geometry since last inspection were found.

4.2 INSTRUMENTATION (257.83(b)(2)(ii))

There is no instrumentation at the Fly Ash Pond.

4.3 IMPOUNDMENT CHARACTERISTICS (257.83(b)(2)(iii, iv, v))

Table 1 is a summary of the minimum, maximum, and present depth and elevation of the impounded water & CCR since the previous annual inspection; the storage capacity of the impounding structure at the time of the inspection; and the approximate volume of the impounded water and CCR at the time of the inspection.

The information in this table is based on visual observations made during the inspection.

Table 1: Fly Ash Pond Characteristics

Approximate Minimum depth (elevation) of impounded water since last annual inspection	None
Approximate Maximum depth (elevation) of impounded water since last annual inspection	None
Approximate Present depth of impounded water at the time of the inspection	No water visible
Approximate Minimum, Maximum, and Present depth (elevation) of CCR since last annual inspection	Ash Depth Varies in Pond from 1 to 30 feet. Unchanged since last inspection.
Storage Capacity of impounding structure at the time of the inspection [crest el]	Approximately 550,000 CY
Approximate volume of impounded water at the time of the inspection	None
Approximate volume of CCR at the time of the inspection	Approximately 500,000 CY

4.4 DEFINITIONS OF VISUAL OBSERVATIONS AND DEFICIENCIES

This summary of the visual observations uses terms to describe the general appearance or condition of an observed item, activity or structure. The meaning of these terms is as follows:

Good: A condition or activity that is generally better or slightly better than what is minimally expected or anticipated from a design or maintenance point of view.

Fly Ash Pond
2025 Annual Dam and Dike Inspection Report
Former Philo Power Plant, Philo, OH

Fair/Satisfactory: A condition or activity that generally meets what is minimally expected or anticipated from a design or maintenance point of view.

Poor: A condition or activity that is generally below what is minimally expected or anticipated from a design or maintenance point of view.

Minor: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is below what is normal or desired, but which is not currently causing concern from a structure safety or stability point of view.

Significant: A reference to an observed item (e.g. erosion, seepage, vegetation, etc.) where the current maintenance program has neglected to improve the condition. Usually conditions that have been identified in the previous inspections, but have not been corrected.

Excessive: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is above or worse than what it is normal or desired, or which may have affected the ability of the observer to properly evaluate the structure or particular area of interest or which may be a concern from a structure's safety or stability point of view.

This document also uses the definition of a “deficiency” as referenced in the CCR rule section §257.83(b)(5) Inspection Requirements for CCR Surface Impoundments. This definition has been assembled using the CCR rule preamble as well as guidance from MSHA, “Qualifications for Impoundment Inspection” CI-31, 2004. These guidance documents further elaborate on the definition of deficiency. Items not identified as a deficiency are considered routine maintenance activities or items to be monitored.

A “deficiency” is some evidence that a dam has developed a condition that could impact the structural integrity of the dam. There are four general categories of deficiencies. These four categories are described below:

1. Uncontrolled Seepage

Uncontrolled seepage is seepage that is not behaving as the design engineer has intended. An example of uncontrolled seepage is seepage that comes through or around the embankment and is not collected and safely carried off by a drain. Seepage that is collected by a drain can still be uncontrolled if it is not safely transported. Seepage that is not clear and is turbid would also be considered as uncontrolled. Seepage that is unable to be measured and/or observe it is considered uncontrolled seepage. [Wet or soft areas are not considered as uncontrolled seepage but can lead to this type of deficiency. These areas should be monitored more frequently.]

2. Displacement of the Embankment

Displacement of the embankment is a large scale movement of part of the dam. Common signs of displacement are cracks, scarps, settlement, bulges, depressions, sinkholes and slides.

3. Blockage of Water Control Appurtenances

Fly Ash Pond
2025 Annual Dam and Dike Inspection Report
Former Philo Power Plant, Philo, OH

Blockage of water Control Appurtenances is the restriction of flow at spillways, decant or pipe spillways, or drains.

4. Erosion

Erosion is the gradual movement of surface material by water, wind or ice. Erosion is considered a deficiency when it is more than a minor routine maintenance item.

4.5 VISUAL INSPECTION (257.83(b)(2)(i))

A visual inspection of the Fly Ash Pond was conducted to identify signs of distress or malfunction of the impoundment and appurtenant structures which includes its hydraulic structures. Specific items inspected included structural elements of the dam such as upstream and downstream slopes, crest, and toe; as well as appurtenances such as the outlet/spillway structure. Photographs taken during the inspection are provided in Attachment B - Photolog.

The following summarizes the visual inspection of the Fly Ash Pond:

1. The upstream and downstream slopes of the Fly Ash Pond are in fair condition. Riprap has been placed in several erosion areas and ATV ruts on the outslope to stabilize them. All of the slopes need vegetation established to stabilize them from erosion.
2. The crest of the dam is in fair condition and is used as an access road. There were no signs of cracks, rutting or low areas.
3. The spillway structure is in poor condition with visible corrosion on the riser, and the outlet appears to be buried in the outslope. The outlet of the spillway should be located and uncovered as part of the pond maintenance, or properly abandoned if no longer needed.
4. The northwest side of the pond dike was originally dry ash storage, and was removed in the past, limiting the overall storage capacity of the pond.

4.6 CHANGES THAT EFFECT STABILITY OR OPERATION (257.83(b)(2)(vii))

There were no changes to the Fly Ash Pond recently that would affect the stability of the impounding structure.

5.0 SUMMARY OF FINDINGS

5.1 GENERAL OBSERVATIONS

The Philo Fly Ash Pond is generally in fair condition. The Fly Ash Pond appears to be functioning as intended with no signs of structural weakness. The spillway outlet pipe should be located and uncovered.

5.2 MAINTENANCE ITEMS

- 1) Vegetation should be established on areas with bare ash.
- 2) The outlet of the spillway should be located and uncovered or properly abandoned if no longer needed.

5.3 ITEMS TO MONITOR/INVESTIGATE

The following items were identified during the visual inspection as items to be monitored or investigated:

- 1) Monitor the spillway riser corrosion to determine if it has the potential to affect the structural integrity.
- 2) Monitor seed and mulch to ensure adequate coverage is established.

5.4 DEFICIENCIES (257.83(b)(2)(vi))

At the Fly Ash Pond there were no signs of structural weakness or disruptive conditions that were observed at the time of the inspection that would require additional investigation or remedial action. There were no deficiencies noted during this inspection or during any of the periodic 7-day or 30-day inspections. A deficiency is defined as: 1) uncontrolled seepage, 2) displacement of the embankment, 3) blockage of control features, or 4) erosion, more than that requiring minor maintenance.

If any of these conditions occur before the next annual inspection contact AEP Ash Management Services immediately.

ATTACHMENT A

Location Map

Philo Fly Ash Pond



Dam and Dike Inspection Report 2025

0 175 350 700 Feet



ATTACHMENT B

Inspection Photos

Fly Ash Pond

2025 Annual Dam and Dike Inspection Report

Former Philo Power Plant, Philo, OH



Photograph 1:

Eastern Dike and Outlet Riser along Fly Ash Pond



Photograph 2:

Western Dike looking north.



Photograph 3:

General View looking east towards outlet riser.

Fly Ash Pond
2025 Annual Dam and Dike Inspection Report
Former Philo Power Plant, Philo, OH



Photograph 4:

Riprap dike repair.



Photograph 5:
Outlet riser.



Photograph 6:

Interior of riser. Note corrosion on lower half.