


Repair [TEST SRR 042825] - 1 - CUMBERLAND RD WEST (2.0 mi)



Click Build to add AS-BUILTs



TEST SRR 042825 CUMBERLAND RD WEST

Info

Report

1333

1301

Job Description

001.00



Click 001.00 to start adding units

001.00



Adders

SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)

R

Quantity: 1

SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)

I

Quantity: 1

Steps

Maint of OH Lines (Labor-SVC)
Z593_SVC-LBR

T

Quantity: 30

LABORONLY

 **This unit can't be deleted****To add unit click Create Adder**

Create Adder

Compatible Unit

Select Unit

Quantity

Comments

Click Select Unit to add unit



Search Compatible Units

Keyword Search:

All

This box is used to search for unit

Filters: [hide](#)

Macro Unit:

SRPI55

Macro Unit will bring up all units in that defined category
SRPI55 is most used capital items

Action:

Action will let you sort between Install Remove or Transfer

[clear](#)

SRPI55

XCO,15kV,100 Amp,10kA

XCO-15-100-10 (SRPI55)

MATLANDLABOR

After you find the unit, click on it

SRPI55

XCO,15kV,100 Amp,10kA

XCO-15-100-10 (SRPI55)

MATLANDLABOR

SRPI55

200W 120V Sodium Floodlight, Yoke, Grey

ALT-200-SFYG (SRPI55)

MATLANDLABOR

SRPI55

200W 120V Sodium Floodlight, Yoke, Grey

ALT-200-SFYG (SRPI55)

MATLANDLABOR

SRPI55

200W 120V Sodium Floodlight, Yoke, Grey

SRPI 55 is used for all
trouble/outage
Voltage and pole size
does not matter

DOP OUTAGES

DO NOT USE
SRPI55

Make sure you have
correct unit
Ex. Pole size,
voltage of
equipment so we
can bill for the
correct equipment

Create Adder

Compatible Unit

SRPI55


SWI,15kV,Line Cutout 1PH,100A,Link

SWI-15-CO1-100-L (SRPI55)

MATLANDLABOR

Quantity

Comments

**Add your quantity**
Cancel

Job Description


Map
Save
Create Adder

Search Compatible Units

Keyword Search:

All

Swi-

Filters: [hide](#)

Macro Unit:

SRPI55

Action:

[clear](#)

SRPI55

SWI,15kV,Line Cutout 1PH,100A,Link

I

SWI-15-CO1-100-L (SRPI55)

MATLANDLABOR

You can only select one at a
time.

SRPI55

SWI,15kV,Line Cutout 1PH,100A,Link

R

SWI-15-CO1-100-L (SRPI55)

MATLANDLABOR

You have to repeat process for
each unit

SRPI55

SWI,15kV,Line Cutout 1PH,100A,Link

T

SWI-15-CO1-100-L (SRPI55)

MATLANDLABOR

Example of searching for Line Fuse Cutout
It will bring up the install, remove, and transfer units

001.00



Adders

SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)

I

Quantity: 1

SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)

R

Quantity: 1

Steps

Maint of OH Lines (Labor-SVC)
Z593_SVC-LBR

T

Quantity: 30

LABORONLY

Make sure to add both units - The remove and install



Job Description



Map



Create Adder

001.00



Adders

SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)
I
Quantity: 1

'H,100A,Link
'I55)

Delete

Complete

Steps

Maint of OH Lines (Labor-SVC)
Z593_SVC-LBR
T
Quantity: 30
LABORONLY



When all units are added and ready to complete, Swipe left on each unit and click complete

001.00



Adders

SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)
I
Quantity: 1



SWI,15kV,Line Cutout 1PH,100A,Link
SWI-15-CO1-100-L (SRPI55)
R
Quantity: 1



Steps

Maint of OH Lines (Labor-SVC)
Z593_SVC-LBR
T
Quantity: 30
LABORONLY



All units should have a check check mark on the right hand side

After all have green check marks - Click the Job Description Button

Job Description

001.00 - Partially Completed: 04/28/2025, 10:04 AM By: s282783



The yellow check mark means the AS-Built is partially complete.

Job Description

partially Completed: 04/28/2025, 10:04 AM By: s282783



Full
Complete

To complete - Swipe left and click the Full Complete Button

If you have completed everything and forgot to add a unit, you can swipe left and incomplete.

This will allow you to go add more units

Job Description

001.00 - Completed: 04/28/2025, 10:04 AM By: s282783



When check mark is Green - that indicates that AS-Builts have been entered and properly captured. If you don't have a green check mark, when you complete ticket the units wont be captured.